WELLS LAMONT

PRODUCT SPECIFICATION SHEET



PRODUCT INFORMATION

Style: VS 10

Part # **Overedge** <u>Size</u> Sizing: White Gray XSmall 135451 135457 Green Small 135452 135458 Yellow Medium 135453 135459 Blue 135454 135460 White Large

XLarge

Registered Brand Name: Whizard® Classification: Cut Resistant



PRODUCT DESCRIPTION

135461

Orange

135455

Description: Wireless Cut Resistant Glove

Color: Available In White or Gray with Blue cuff
Material: High Performance Fibers; Wireless
CFR 21 - Approved for Food Contact

Sold by: Piece
Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 120 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F1790-97
Test Results: 2432 grams / 5.36lbs.

ANSI Level 4

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-05
Test Results: 3100 revs (cycles)

WASHING INSTRUCTIONS

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If presoaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714
Toll-Free 1.800.247.3295 Fax 1.847.470.1026 www.wellslamontindustrial.com

JC 7/12