WELLS LAMONT

Industrial

# PRODUCT SPECIFICATION SHEET



## PRODUCT INFORMATION

Style: Medium Duty Armguard

Size Part #

**Sizing:**10" 333477

20" 333480 with clip 22" 333482 with clip

Registered Brand Name: Whizard®
Classification: Cut Resistant



**Description:** Medium Duty Cut Resistant Sleeve

Color: Gray

Material: Combination of High Performance Fibers and Stainless Steel

CFR 21 - Approved for Food Contact

Sold by: Piece
Packaging (Inner Pack): 1 Piece
Packaging (Case Pack): 50 Pieces

## **CUT PROTECTION PERFORMANCE INFORMATION**

 Test Method:
 ASTM F1790-97

 Test Results:
 3,152 grams / 6.95lbs.

ANSI Level 4

## WASHING INSTRUCTIONS

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If pre-soaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

### CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714

Toll-Free 1.800.247.3295 Fax 1.847.470.1026 www.wellslamontindustrial.com

JC 7/12