

**PRODUCT INFORMATION****Style:** Defender Armguard

<b>Sizing:</b>	<u>Size</u>	<u>Part #</u>	
	10"	133680	
	22"	133683	(with clip)

**Registered Brand Name:** Whizard®  
**Classification:** Cut Resistant**PRODUCT DESCRIPTION****Description:** Defender Armguard Sleeve  
**Color:** Blue  
**Material:** High Performance Yarns with Stainless Steel  
CFR 21 - Approved for Food Contact**Sold by:** Piece  
**Packaging (Inner Pack):** 1 Piece  
**Packaging (Case Pack):** 50 Pieces**CUT PROTECTION PERFORMANCE INFORMATION****Test Method:** ASTM F1790-97  
**Test Results:** 3171 grams / 6.98lbs.  
ANSI Level 4**WASHING INSTRUCTIONS**

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If pre-soaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

**CAUTION**

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714  
Toll-Free 1.800.247.3295 Fax 1.847.470.1026 [www.wellslamontindustrial.com](http://www.wellslamontindustrial.com)

JC 7/12