

DANGER
FACE SHIELD MUST BE WORN WHEN OPERATING THIS MACHINE

PS 10 x 14 D527PB
RP 10 x 14 D527RB
AL 10 x 14 D527AB

DANGER
FACE SHIELD REQUIRED WHEN OPERATING THIS EQUIPMENT

PS 7 x 10 D274P
PS 10 x 14 D274PB
RP 7 x 10 D274R
RP 10 x 14 D274RB
AL 10 x 14 D274AB

DANGER
FALL PROTECTION REQUIRED BEYOND THIS POINT

PS 10 x 14 D528PB
RP 10 x 14 D528RB
AL 7 x 10 D528A
AL 10 x 14 D528AB

DANGER
FALL PROTECTION REQUIRED IN THIS AREA

PS 10 x 14 D529PB
RP 10 x 14 D529RB
AL 7 x 10 D529A
AL 10 x 14 D529AB

DANGER
FALLING ICE

PS 10 x 14 D530PB
RP 10 x 14 D530RB
AL 10 x 14 D530AB

DANGER
FALLING MATERIALS

RP 7 x 10 D37R
RP 10 x 14 D37RB
AL 7 x 10 D37A

DANGER
FLAMMABLE

PS 7 x 10 D126P
PS 10 x 14 D126PB
RP 7 x 10 D126R
RP 10 x 14 D126RB
AL 7 x 10 D126A
AL 10 x 14 D126AB
FG 10 x 14 D126EB

DANGER
FLAMMABLE 

PS 10 x 14 D531PB
RP 10 x 14 D531RB
AL 10 x 14 D531AB

DANGER
FLAMMABLE GAS

PS 7 x 10 D276P
PS 10 x 14 D276PB
RP 7 x 10 D276R
RP 10 x 14 D276RB
AL 7 x 10 D276A
AL 10 x 14 D276AB

DANGER
FLAMMABLE KEEP FIRE AWAY

PS 7 x 10 D417P
PS 10 x 14 D417PB
RP 7 x 10 D417R
RP 10 x 14 D417RB
AL 7 x 10 D417A
AL 10 x 14 D417AB

DANGER
FLAMMABLE KEEP FLAMES AND HEAT AWAY

PS 10 x 14 D532PB
RP 10 x 14 D532RB
AL 10 x 14 D532AB

DANGER
FLAMMABLE LIQUIDS

PS 7 x 10 D38P
PS 10 x 14 D38PB
RP 7 x 10 D38R
RP 10 x 14 D38RB
AL 7 x 10 D38A
AL 10 x 14 D38AB
FG 10 x 14 D38EB

DANGER
FLAMMABLE LIQUIDS NO SMOKING

PS 10 x 14 D645PB
RP 10 x 14 D645RB
AL 10 x 14 D645AB

DANGER
FLAMMABLE MATERIAL NO SMOKING OR OPEN FLAMES

PS 7 x 10 D117P
PS 10 x 14 D117PB
RP 7 x 10 D117R
RP 10 x 14 D117RB
AL 7 x 10 D117A
AL 10 x 14 D117AB
FG 10 x 14 D117EB

DANGER
FLAMMABLE MATERIAL NO SMOKING WITHIN 20 FEET

PS 7 x 10 D438P
PS 10 x 14 D438PB
RP 7 x 10 D438R
RP 10 x 14 D438RB
AL 7 x 10 D438A
AL 10 x 14 D438AB

DANGER
FLAMMABLE MATERIALS

PS 7 x 10 D39P
PS 10 x 14 D39PB
RP 7 x 10 D39R
RP 10 x 14 D39RB
AL 7 x 10 D39A
AL 10 x 14 D39AB
FG 10 x 14 D39EB

DANGER
FLAMMABLE NO MATCHES OR OPEN LIGHTS

PS 10 x 14 D533PB
RP 10 x 14 D533RB
AL 10 x 14 D533AB

DANGER
FLAMMABLE NO SMOKING

PS 10 x 14 D663PB
RP 10 x 14 D663RB
AL 10 x 14 D663AB

DANGER
FLAMMABLE NO SMOKING, MATCHES OR OPEN LIGHTS

PS 10 x 14 D646PB
RP 10 x 14 D646RB
AL 10 x 14 D646AB

DANGER
FLAMMABLE STORAGE

PS 10 x 14 D534PB
RP 10 x 14 D534RB
AL 7 x 10 D534A
AL 10 x 14 D534AB

DANGER
FOLLOW CONFINED SPACE ENTRY PROCEDURE BEFORE ENTERING

PS 7 x 10 D277P
PS 10 x 14 D277PB
RP 7 x 10 D277R
RP 10 x 14 D277RB
AL 7 x 10 D277A
AL 10 x 14 D277AB



D534


DANGER
FOLLOW LOCKOUT/TAG OUT PROCEDURES 

PS 10 x 14 D535PB
RP 10 x 14 D535RB
AL 10 x 14 D535AB

Size	PS Pressure Sensitive Vinyl		RP .050 Rigid Plastic		AL .040 Aluminum		FG Fiberglass	
	1 - 5	6+	1 - 5	6+	1 - 5	6+	1 - 5	6+
7" x 10"	\$5.24	\$4.44	\$7.07	\$6.00	\$14.24	\$13.67	-	-
10" x 14"	\$6.58	\$5.60	\$10.49	\$8.91	\$18.36	\$15.60	\$21.31	\$18.13

Determining Header Selection Guide

OSHA and ANSI requires signage to indicate and define specific hazards that, without identification, may lead to injury or death. Select your sign with the header that indicates the degree of hazard in your application.



Use **DANGER** to indicate an immediate hazard which has a high probability to severe injury or death.



Use **WARNING** to indicate a potentially hazardous situation which, if not avoided, can result in serious injury or death.



Use **CAUTION** to indicate a potentially hazardous situation which may result in minor or moderate injury, but not death.



Use **NOTICE** to provide general information needed to avoid confusion.



These and similar headings are used with information about housekeeping, first aid, health, medical equipment, sanitation and general safety.



» Guide to Sign Legibility

Viewing Distance	Letter Height
30'	3/4"
40'	1"
55'	1 1/4"
65'	1 1/2"
75'	1 3/4"
85'	2"
115'	2 1/2"
135'	3"
150'	4"
200'	6"
350'	8"

Determine the viewing distance for your sign, then contact our Inside Sales Team and we'll do the rest!

