WELLS LAMONT

Industrial

PRODUCT SPECIFICATION SHEET



PRODUCT INFORMATION

Style: Silver Talon with Grip Pattern

Sizing:	<u>Size</u>	Part #		<u>Overedge</u>
		<u>Left</u>	<u>Right</u>	
	XXSmall	134656	134657	Red
	Xsmall	134659	134660	Green
	Small	134662	134663	Yellow
	Medium	134665	134666	Blue
	Large	134668	134669	White
	XLarge	134671	134672	Orange



Registered Brand Name: Whizard® Classification: Cut Resistant

PRODUCT DESCRIPTION

Description: High Performance Cut Glove with Grip Pattern

Color: Gray Shell / Green Pattern

Material: Patented Yarn Composition of High Performance Fibers and Stainless Steel

Palm: Polyurethane Pattern

Sold by: Piece Packaging (Inner Pack): 6 Pieces Packaging (Case Pack): 72 Pieces

CUT PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM F1790-97 Test Results: 3,713 grams / 8.1 lbs.

ANSI Level 5

ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-05 Test Results: 2688 revs (cycles)

WASHING INSTRUCTIONS

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If pre-soaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

CAUTION

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714

Toll-Free 1.800.247.3295 Fax 1.847.470.1026 www.wellslamontindustrial.com