**WELLS LAMONT** 

Industrial

# PRODUCT SPECIFICATION SHEET



## PRODUCT INFORMATION

Style: Defender 7

Size Part # Overedge Sizina: Std. Cuff Ext. Cuff XSmall 135484 135437 Green Small 135485 135438 Yellow Medium 135486 135439 Blue White Large 135487 135440 XLarge 135488 135441 Orange

Registered Brand Name: Whizard®
Classification: Cut Resistant

## PRODUCT DESCRIPTION

**Description:** High Performance Antimicrobial Cut Glove

Color: White Shell / Yellow Cuff

Material: Patented Combination Of High Performance Fibers And Stainless Steel; Antimicrobial

CFR21 - Approved for Food Contact

Cuff: Regular or Extended

Sold by: Piece
Packaging (Inner Pack): 6 Pieces
Packaging (Case Pack): 72 Pieces

### **CUT PROTECTION PERFORMANCE INFORMATION**

Test Method: ASTM F1790-97
Test Results: 4,229 grams / 9.32 lbs.

ANSI Level 5

### ABRASION PROTECTION PERFORMANCE INFORMATION

Test Method: ASTM D3884-05
Test Results: 10,045 revs (cycles)

# **WASHING INSTRUCTIONS**

Always wash similar products of the same materials together. This will eliminate different material types from being effected by non-recommended chemicals. Rinse all gloves thoroughly in cold water to ensure the release of particles in the products. If presoaking use luke warm water to ensure good particle softening. Mild detergents or chemicals should be used to enhance the laundering process. All products should be laundered using a mild soap and detergent. Use a warm water wash with a temperature not to exceed 160°F (71°C). Wash time should not be longer than 15 to 20 minutes. Use a rinse cycle for the product in cold water. Repeat above as often as needed to ensure a thoroughly clean product. It is important to use a high extraction speed to thoroughly remove all excess moisture. Tumble dry glove in a temperature not higher than 150°F (67°C) for a time of 15 to 20 minutes; adjustments in dry time may increase depending on quantity and weight of the products. Temperatures should not exceed 150°F (67°C).

### **CAUTION**

Gloves are cut resistant but are not cut or puncture-proof. Do not subject to high-speed, serrated blades or intentional slashings.

Wells Lamont Industrial 6640 W Touhy Ave Niles IL 60714
Toll-Free 1.800.247.3295 Fax 1.847.470.1026 www.wellslamontindustrial.com